



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 19799129	Plate Category	: PRIVATE
Transaction Date	: 18 MAY 2020 09:31:19	Plate Number	: D87734 EA
Queue Number	: 178189	Import Doc. Ref.	:
Chassis Number	: WBAYE8104DDD87734	Manufacturer/Model	: BMW/750 LI
Engine Number	:	Model Year	: 2013
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: GREY
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.07 - Floor		الارضية
05.08 - Chassis (Frame)		الشاصية
06 General Items		الاشياء العامة
06.14 - Transmission Condition	OK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	OK	حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.10 - Engine Oil Leaking		تهريب زيت المحرك
09.25 - Body Repainted		أثر صيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		

# Test Certificate

PASS




Possession Certificate :	64271785	
Chassis No :	WBAYE8104DDD87734	
Vehicle Make :	BMW	
Vehicle Model :	750LI	
Vehicle Class :	Light Vehicle	
Body Type :	SALOON	
Fuel :	Benzene	
Color :	Gray	
Drive Direction :	--	
Dimensions : (H x W x L) -- x -- x --		
Current Odometer :	127499 Kms.	
Origin :	Germany	Model Year :
Gear Type :	--	2013
Engine No :	20550289	Engine Size :
Axles No :	2	5000 CC
No Of Doors : 4		Horse Power :
G. V. W. :	2000 Kgs.	449
		Cylinders :
		8
		No Of Seats :
		5
		Empty Weight :
		1450 Kgs.

Certificate Number :	5-TAS-2020-11986515	
Inspection Date :	20-05-2020	
Certificate Print Date :	20-05-2020	
Services :	Registration Test	
Vehicle Testing Partner :	Tasjeel	
Vehicle Testing Center :	Tasjeel Emirates Auction	
Total Time Taken :	17 min 7 sec	
Appointment Ref Number :	--	
Start Time :	End Time :	
12:21	12:38	
Lane :	Token No. :	
01	3	
Attempt :	Prints No. :	
1	1	

## Carbon footprint



## Estimated Vehicle Consumption ( Rate last 12 Months )



## Parameter Readings

Service brake imbalance on front axle 4 %	Service brake imbalance on rear axle 7 %	Parking brake imbalance between LHS and RHS 6 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 7 PPM VOL			

## Inspection Remarks:

REAR COMPARTMENT PANEL AND REAR BOTH SIDE CHASSIS EXTENSION REPLACED//MINOR DENTS AND SCRATCHES

## Payment Details

Inspection Performed by 62403	Payment Method VTP Credit Account	Transaction Number 11986515	Service Fees AED 170 Collected on 20/05/2020
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Gilbert De Guzman Balatero

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صادرة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and

