

Queue Number 2837258

Transaction Date 12 Oct 2026, 16:47:28

Site Name
840 - Emirates AuctionsTransaction Number
72197869 (CC10010) (CC10010)

Vehicle Details

Chassis Number JHMF16278*****
 Specification GCC Specification
 Make Honda
 Model Civic
 Model Year 2008
 Color Silver
 Mileage 268341 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED PORTION REPAIRED PORTION GETTING RUSTY FADED MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS MUDDY	الارضية
01.D Bumper	MISALIGN ,SCRATCHES, PORTION DAMAGED	دعامية
01.E Bonnet	DAMAGED.	غطاء المحرك
01.F Sign of front accident	FRONT BUMPER FRAME ,FENDER FRAME , RADIATOR SUPPORT BULK HEAD ,CROSS MEMBER INNER FENDER FRAME REPAIRED .	وجود مؤشر لحادث في المقدمة
01.G Sign of back accident	BACK PANEL QUARTER PANEL COMPARTMENT AREA REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS,REAR BOTH SIDE CHASSIS EXTENSION END REPAIRED DENT ,GETTING RUSTY.	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CRAKED .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECK REFITTED OIL LEAK ,PARTS RUSTY .	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	DIRTY LOOSE PORTION CUT .	حالة المقاعد
---------------------	---------------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition الجير		
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK ,PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition الاطارات		
06.A Front Tyre	EXPIRED CRACKED WORN OUT	الاطار الامامي
06.B Rear Tyre	EXPIRED CRACKED WORN OUT	الاطار الخلفي
07 Lights الاضاءة		
07.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
07.B Tail Light	PORTION CRACKED LOOSE	الضوء الخلفي
08 Brake Condition الفرامل		
08.A Disc&Drum	PARTS RUSTY.	دسك و طناوير الفرامل
09 Suspension System ممتص الصدمات		
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED.	ازرع
10 Interior Condition الحالة الداخليه		
10.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED.	اخرى
10.B Mirror	LOOSE FADED.	المرايا
10.C AC Condition	NOT CHECKED .	المكيف
10.D Dash Board	PORTION LOOSE.	لوحة القيادة
10.E Sun Visor	LOOSE.	حاجب الشمس
10.F Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT PORTION LOOSE.	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on

لشكاوي والمقترحات يمكنك التواصل معنا عبر

