



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>11 Jan 2022, 18:15:29</b>
Transaction Number	<b>93601782 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WBA4A1103FD401124</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>BMW</b>
Model	<b>420 I</b>
Model Year	<b>2015</b>
Color	<b>White</b>
Mileage	<b>107730 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	LEFT SIDE BOTH REPAINTED,PORTION REPAIRED,FRONT LEFT SIDE REFITTED	مدكار
01.B Bumper	REPAINTED	دعامية
01.C Sign of side accident		وجود مؤشر لحادث في الجانب
01.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.E Floor	UNDER BODY FULLY COVERED	الارضية
01.F Doors	LEFT SIDE BOTH REPAINTED & REAR PORTION REPAIRED	أبواب
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Engine Condition	OK	حالة المحرك
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Gear Box	OK	الجير
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A AC Condition	OK	المكيف
<b>05 Wipers and Arms</b>		<b>المساحات</b>

DEFECT	REMARKS	
05.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
<b>06 Seats Condition</b>		<b>المقاعد</b>
06.A Seat Belt	OK	حزام الأمان
06.B Seat Condition	OK	حالة المقاعد
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	VISIBLE AREA OK	الشاسيه
<b>08 Brake Condition</b>		<b>الفرامل</b>
08.A Disc&Drum	GETTING RUSTY	دسك ووطنابير الفرامل
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
09.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
<b>10 Battery Condition</b>		<b>حالة البطارية</b>
10.A Battery Condition	OK	حالة البطارية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.