

Queue Number

2409017

Transaction Date

21 May 2026, 15:09:17

Site Name

840 - Emirates Auctions

Transaction Number

96213208 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JN8AY2NYOP*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2023
Color	Black
Mileage	98044 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REFITTED, REAR LEFT REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS SCRATCHES, PORTION GETTING FADED RUSTY	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DIRTY FOR FULL INSPECTION MAKE STEAM WASH FOR RECHECK	الارضية
01.F Bumper	MISALIGN, REAR PARKING SENSOR MISSING	دعامية
01.G Windshield	DAMAGED	زجاج
01.H Bonnet	REFITTED	غطاء المحرك
01.I Other	BODY LEVEL LOW	اخرى
01.J Fuel Tank	DENT	خزان الوقود

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME DIRTY MUDDY GETTING RUSTY	الشاسيه
02.B Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS GETTING RUSTY , MUDDY	الحالة النظرية للمحرك
------------------------------	-----------------------------	-----------------------

04 Exhaust System

نظام العادم

Condition	Remarks	الحالة
04.A Other	DENT	اخرى
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص على الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2022 DRY CRACK	الاطار الامامي
06.B Rear Tyre	2022 DRY CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	LEFT SIDE PORTION CRACKED	الضوء الخلفي
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.C Fog light	NOT WORKING	كشف الضباب
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Hydraulic System	NOT WORKING	النظام الهيدروليكي
10 Steering Condition		المقود
10.A Steering Oil	MINOR OIL LEAK	زيت المقود
10.B Steering Boot	BOOT CUT LEAK	ربلة المقود
10.C Tie Rod End	BOOT CUT	مؤخرة الرودادات
11 Interior Condition		الحالة الداخلية
11.A Other	COOL BOX NOT WORKING / INTERIOR PARTS GETTING RUSTY	اخرى
11.B Mirror	CENTER VIEW MIRROR MISSING	المرايا
11.C AC Condition	OK	المكيف
11.D Roof Ceiling	PORTION CUT	بطانة السقف
11.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae