



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Jul 2022, 18:09:20
Transaction Number	78710120 (CC10006)	Queue Number	312309



Chassis Number	JN8AY2NY2G9215364
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2016
Color	Grey
Mileage	166973 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Bonnet	REPAINTED & REFITTED	غطاء المحرك
01.B Doors	REAR RIGHT SIDE PORTION REPAIRED, REPAINTED	أبواب
01.C Other	FRONT FENDER FRAME, RADITOR SUPPORT , BULK HEAD,BUMPER FRAME REPAIRED	اخرى
01.D Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.E Rusty	UNDER BODY PARTS, SUSPENTION , CHASSIS FRAME GETTING RUSTY	صدأ
01.F Trunk	TRUNK NOT OPEN FOR CHECK	صندوق
01.G Sign of front accident		وجود مؤشر لحادث في المقدمة
01.H Fenders	FRONT BOTH SIDE REPAINTED REFITTED & REAR BOTH SIDE PORTION REPAIRED REPAINTED	مدكار
01.I Floor	LEFT SIDE BODY MOUNT REPAIRED	الارضية
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK	المكيف
02.B Mirror	NOT WORKING & LOOSE	المرابا
02.C Steering Wheel and control buttons	HORN NOT WORKING	عجلة القيادة وازرار التحكم

DEFECT	REMARKS	
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03.C Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
04 Transmission Condition		الجير
04.A DIFFERENTIAL	FRONT OIL LEAK	الدفرنشيل
04.B Road Test	NOT CHECK	فحص علي الطريق
04.C Visual Gear Box Condition	OK	حالة الجير النظري
05 Engine Condition		المحرك
05.A Smoke	MINOR BLACK SMOKE	دخان
05.B Visual Engine Condition	OIL WET & REFITTED	حالة المحرك النظري
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07 Chassis Condition		الشاصي
07.A Chassis	LEFT SIDE CHASSIS FRONT & REAR HEATED REPAIRED, RIGHT SIDE ALIGN REPAIRED, DENT	الشاسيه
08 Seats Condition		المقاعد
08.A Seat Belt	REAR RIGHT SIDE NOT WORKING	حزام الأمان

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.



✓ PASS

Plate Details :	--
Chassis No :	JN8AY2NY2G9215364
Vehicle Make :	NISSAN
Vehicle Model :	PATROL LE PLATINUM CITY
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Gray
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	166967 Kms.
Origin : Japan	Model Year : 2016
Gear Type : Automatic	Engine Size : 5600 CC
Engine No : VK56169548A	Horse 400
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 8
G. V. W. : 2900 Kgs.	Empty 1900 Kgs.
	Weight :

Certificate Number :	5-TAM-2022-17221437		
Inspection Date :	18-07-2022		
Certificate Print Date :	18-07-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tamam		
Vehicle Testing Center :	Tamam Vehicles Testing		
Total Time Taken :	9 min 20 sec		
Appointment Ref Number :	--		
Start Time :	11:45	End Time :	11:54
Time :		Token No. :	107
Lane :	02	Prints No. :	1
Attempt :	1		

Carbon footprint



Keep protecting Dubai environment

Estimated Vehicle Consumption (Rate in 12 Months)

18551 KM	1909 L	5995 AED	4.6 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
1 %	8 %	2 %	0.42 %
Vehicle on Petrol HC Reading			
30 PPM VOL			

Inspection Remarks: FRONT LHS MIDDLE CHASSIS HEATED & REPAIRED CCM OK //RADIATOR FRAME, FENDER FRAME REPAIRED

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
2027	Cash	17221437	AED 170 Collected on 18/07/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Floribel Flores Sepulvida

① This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.