CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2998608
Transaction Date	17 Nov 2026, 14:04:35
Site Name	840 - Emirates Auctions
Transaction Number	15496585 (CC10009) (CC10019)



Vehicle Details

Chassis Number	JN8FY1NY5E*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2014
Color	Silver
Mileage	207254 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED,PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	BODY MOUNT BEND/ FLOOR CHASSIS COMPLETELY THICK RUST PROOFED,PORTION DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	REPAINTED,	السقف
01.H Bonnet	REPAINTED,PORTION REPAIRED,REFITTED, SHOCK WEAK	غطاء المحرك
01.I Trunk	NOT OPENING, LOCK DAMAGED	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS SLIGHTLY BEND REAR BOTH SIDE BULGED MINOR DENT, THICK RUST PROOFED	الشاسيه
02.B Chassis Number	RUST PROOFED/ CHECKED ON PLATE	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Smoke	MINOR WHITE	دخان
03.B Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY, SHAKING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**

Condition	Remarks	الحالة
04.A Seat Condition	EXTRA COVER PORTION CRACKED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B DIFFERENTIAL	REAR OIL LEAK	الدفرنشل
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020 EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Steering Condition		المقود
08.A Axle	ROMANA LEAK	اكسلات
09 Interior Condition		الحاله الداخليه
09.A Other	INETRIOR PARTS GETTING RUSTY	اخري
09.B AC Condition	NOT COOLING	المكيف
09.C Door Panel	WORN OUT, LOOSE	لوحة بطانة الباب
09.D Steering Wheel and control buttons	HORN NOT WORKING	عجلة القيادة وازرار التحكم
09.E Sunroof	NOT WORKING	فتحت سقف
09.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae