CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934053
Transaction Date	04 Nov 2026, 14:27:21
Site Name	840 - Emirates Auctions
Transaction Number	52689842 (CC10010) (CC10010)



Vehicle Details

Chassis Number	55SWF4JBXF*******
Specification	Imported
Make	Mercedes
Model	C 300
Model Year	2015
Color	Silver
Mileage	158521 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT & REAR BOTH SIDE REPAINTED PORTION REPAIRED. FRONT BOTH SIDE REFITTED .	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.E Bumper	MISALIGN SCRATCHES . PORTION DAMAGED ,REAR TOWHOOK COVER MISSING.	دعامية
01.F Bonnet	REFITTED .	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD REPAIRED , ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
01.H Sign of side accident	QUARTER PANEL ,WHEEL ARCH REPAIRED.	وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA,PORTION DENT.	الشاسيه
02.B Other	NEED TO REMOVE FENDER UNDER COVER FOR RECHECK.	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED , PARTS RUSTY ,MINOR OIL LEAK .	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,PARTS RUSTY ,UNDER PORTION COVERED	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2023 WORN OUT CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 WORN OUT CRACKED	الاطار الخلفي
05.C Rims Condition	MINOR SCRATCHES .	حالة الجنوط
06 Suspension System		**ممتص الصدمات**
06.A Shock Absorber	MINOR LEAK .	ممتص الصدمات
06.B Arms	BUSHES CRACKED.	ازرع
07 Interior Condition		**الحاله الداخليه**
07.A Other	INTERIOR ACCESSORIES NOT CHECKED .	اخري
07.B AC Condition	NOT CHECKED .	المكيف
07.C Steering Wheel and control buttons	GETTING WORN OUT .	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae