



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	01 Sep 2021, 13:39:01
Transaction Number	99286582 (CC10007)	Queue Number	312309



Chassis Number	JMYSRCY1AFU724785
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	Lancer
Model Year	2015
Color	White
Mileage	206288

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	LEFT SIDE BOTH & REAR RIGHT SIDE PORTION REPAIRED, REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	LEFT SIDE BOTH DOOR, REAR TRUNK PORTION REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	REAR BACK PANEL, SPARE WHEEL HOUSING , BULKHEAD REPAIRED & BUMPER FRAME BEND	الارضية
01.F Bumper	REPAINTED & MISALIGN	دعامية
01.G Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
01.H Other	FRONT FENDER FRAME, RADITOR SUPPORT, BUMPER FRAME , BULKHEAD REPAIRED	اخرى
01.I Pillars	LEFT SIDE A/PILLAR, ROCKER PANEL, RUNNING BOARD & WHEEL HOUSING REPAIRED	القوائم
02 Chassis Condition		الشاسي
02.A Chassis	FRONT BOTH SIDE END REPAIRED & LEFT SIDE INNER KINK	الشاسيه
03 Seats Condition		المقاعد
03.A Other	OK	اخرى
04 Tires and Rims Condition		الاطارات

DEFECT	REMARKS	
04.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
05 Wipers and Arms		المساحات
05.A Other	WORN OUT	اخرى
06 Lights		الاضاءة
06.A Head Light	OK	الاضاءة الرئيسية
06.B Other	OK	اخرى
07 Brake Condition		الفرامل
07.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES DRY CRACKED	ازرع
08.B Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY	
09 Interior Condition		الاجزاء الداخلية
09.A Other	OK	اخرى
09.B Mirror	OK	المرايا
09.C AC Condition	A/C NOT COOLING	المكيف
10 Transmission Condition		الجير
10.A Gear Box Mount	BUSHES CUT	كرسي الجير
11 Engine Condition		المحرك
11.A Mount	BUSHES CUT	كرسي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.