

Queue Number	2819322	Transaction Date	30 Sep 2026, 14:59:53
Site Name	840 - Emirates Auctions	Transaction Number	29724985 (CC10006) (CC10006)



Vehicle Details

Chassis Number	WBA6B2102D*****
Specification	GCC Specification
Make	BMW
Model	650 i
Model Year	2013
Color	Grey
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		
جسم المركبة		
01.A Fenders	FRONT BOTH SIDE FIBER PAINT CANNOT CHECK, REAR RIGHT SIDE REPAINTED, PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERD, OILY, MUDDY, COVER PORTION DAMAGED	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	SHOCK WEAK	غطاء المحرك
02 Chassis Condition		
الشاسي		
02.A Chassis	COVERD, OILY, MUDDY, CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		
المحرك		
03.A Mount	BUSHES CRACKED	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		
الجير		
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
04.B Gear Box Mount	BUSH CRACKED	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021/2022 DRY CRACKED	الاطار الخلفي
06 Suspension System		ممتص الصدمات
06.A Shock Absorber	LEAK	ممتص الصدمات
06.B Ball Joint	BOOT CUT	مفصل كروي
07 Steering Condition		المقود
07.A Steering Box	LEAK	جهاز المقود
07.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
07.C Axle	BOOT CUT	اكسلات
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED. INTERIOR COVER MODIFIED	اخرى
08.B AC Condition	NOT CHECK	المكيف
08.C Dash Board	COVER PORTION DAMAGED	لوحة القيادة
08.D Roof Ceiling	LOOSE , PORTION DAMAGED	بطانه السقف
08.E Odometer reading	NOT CHECK	قراءة عداد المسافات
08.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae