CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906028
Transaction Date	27 Oct 2026, 15:17:25
Site Name	840 - Emirates Auctions
Transaction Number	56395461 (CC10010) (CC10011)



Vehicle Details

Chassis Number	WBAJL1106J*******
Specification	GCC Specification
Make	BMW
Model	520
Model Year	2018
Color	Blue
Mileage	447872 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY TOTALLY STICKER PAINT NOT CHECK,STICKER CRACKED CUT PORTION FADED DENTS	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.D Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Sign of front accident	FRONT ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED PORTION DENT , CHECKED ONLY VISIBLE AREA .	الشاسيه
02.B Other	NEED TO REMOVE FENDER UNDER COVER COVER FOR INSPECTION .	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION WORN OUT,FRONT SEATS BACK COVER PORTION DAMAGED LOOSE	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE DAMAGED EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE DAMAGED EXPIRED	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	BODY LEVEL VERY LOW.	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CRACKED .	ربلة المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX COVER PORTION WORN OUT,INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECK,GRILL ADJUSTER MISSING	المكيف
11.C Roof Ceiling	LOOSE	بطانه السقف
11.D Door Panel	PORTION MELTED LOOSE WORN OUT	لوحة بطانة الباب
11.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر

wecare@carscheck.ae