

TEST CERTIFICATE

Site Number
Transaction Number

04.C Doors

05.B Arms

840-Emirates Auctions 38413755 (CC10006) Transaction Date

21 Sep 2022, 12:23:35

Queue Number 593834

Chassis Number

SALGA2BEXJA503300

Engine Number

Vehicle Class Car

Manufacturer Range Rover

Model Autobiography

Model Year 2018
Color Grey

Mileage **64170 Km**Fuel Type **Petrol**

No. Of Cylinders

Specification

GCC Specification



01 Chassis Condition الشاصي 01.A Chassis CHECKED ONLY VISIBLE AREA OK. الشاسيه **02 Engine Condition** المحرك ОК 02.A Visual Engine Condition حالة المحرك النظرى **03 Transmission Condition** الجير 03.A Visual Gear Box OK حالة الجير النظرى Condition 03.B Road Test **NOT CHECK** فحص على الطريق 04 Body جسم المركبة UNDER FLOOR PORTION COVER, CHECKED VISIBLE AREA 04.A Floor الارضية 04.B Paint **BODY PORTION REPAINTED MINOR, SCRATCHES** الصبغ

O5 Suspension Systemممتص الصدمات05.A Ball JointBOOT CUT

REAR LEFT SIDE REPAINTED

LOWER ARM BUSHES CRACKED

ازرع

أبواب

DEFECT	REMARKS	
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
07 Interior Condition		الحاله الداخليه
07.A AC Condition	ОК	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.