CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3002583
Transaction Date	17 Nov 2026, 16:51:40
Site Name	840 - Emirates Auctions
Transaction Number	88206317 (CC10013) (CC10011)



Vehicle Details

Chassis Number	MDHBN7AD2M*******
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2021
Color	White
Mileage	216489 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT,REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUST PROOFED DENT	الارضية
01.E Bumper	MISALIGN PORTION CRACK	دعامية
01.F Trunk	PORTION REPAIRED REPAINTED,COMPARTMENT COVER DAMAGED	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME BEND / ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH FOR RECHECK	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL PAN DENT , COMPONENTS REFITTED , OIL LEAK	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT BOTH SEAT SIDE COVER LOOSE PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	JERKING , OIL PAN DENT OIL LEAK , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2021 CRACKED EXPIRED,RIGHT 2022 CRACK	الاطار الامامي
06.B Rear Tyre	LEFT SIDE,RIGHT 2023 CRACK	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	CAP MISSING	اخري
08 Lights		الاضاءة
08.A Head Light	LENS FADED,RIGHT SIDE BRACKET DAMAGED REPAIRED	الاضاءة الرئيسية
08.B Tail Light	LEFT SIDE PORTION DAMAGED	الضوء الخلفي
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	REAR CONSOLE BOX BRACKET DAMAGED / INITERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
10.B Mirror	ADJUSTMENT NOT WORKING	المرايا
10.C AC Condition	OK	المكيف
10.D Audio	LCD DAMAGED	صوتيات
10.E Door Panel	FRONT LEFT SIDE PORTION CRACKED	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11 Battery Condition		حالة البطارية
11.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae