



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 May 2023, 11:21:16
Transaction Number	85593329 (CC10008)	Queue Number	727421



Chassis Number	JTHBL46F275001228
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	LS 460
Model Year	2007
Color	Black
Mileage	001 NA
Fuel Type	Petrol
No. Of Cylinders	8
Specification	Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Bumper	REAR MISSING	دعامية
01.B Sign of side accident		وجود مؤشر لحادث في الجانب
01.C Windshield	REAR CURTAIN NOT WORKING	زجاج
01.D Fenders	FRONT REFITTED	مدكار
01.E Pillars	RIGHT SIDE C/PILLAR,ROCKER PANEL REPAIRED & RIGHT SIDE A/PILLAR INNER COVER LOOSE	القوائم
01.F Floor	PORTION DENT & UNDER FLOOR COVERED	الارضية
01.G Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED ,	الصبغ
01.H Other	FRONT RIGHT SIDE FENDER COVER & UNDER ENGINE COVER MISSING & RADIATOR LOWER SUPPORT BEND	اخرى
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK,GRILL PORTION CRACKED	المكيف
02.B Mirror	AUTO FOLDING NOT WORKING & RIGHT SIDE DAMAGED	المرآيا
02.C Dash Board	PORTION DAMAGED,MELTED	لوحة القيادة
02.D Sunroof	NOT WORKING	فتحت سقف
02.E Roof Light	CONSOLE BOX LOOSE	أنارة السقف

DEFECT	REMARKS	
02.F Other	CENTER CONSOLE BOX SIDE PANEL PORTION DAMAGED & GEAR LEVER DUST COVER MISSING	اخرى
02.G Roof Ceiling	PORTION LOOSE	بطانه السقف
03 Tires and Rims Condition		الاطارات
03.A Rear Tyre	BOTH SIDE 2016 CRACKED , EXPIRED ,	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED,RIGHT SIDE PUNCTURE ,DAMAGED	الاطار الامامي
03.C Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
03.D Rims Condition	DENT,SCRATCHES,REAR RIGHT SIDE DAMAGED& FRONT RIGHT SIDE HUB COVER MISSING	حالة الجنوط
04 Steering Condition		المقود
04.A Tie Rod	FRONT RIGHT SIDE BROKEN	رودات
04.B Tie Rod End	BOOT CUT	مؤخرة الرودات
05 Engine Condition		المحرك
05.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
05.B Smoke	BLACK SMOKE	دخان
06 Lights		الاضاءة
06.A Head Light	LENS FADED & LOW,HIGH BEAM NOT WORKING	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
07 Seats Condition		المقاعد
07.A Seat Condition	EXTRA COVER	حالة المقاعد
08 Transmission Condition		الجير
08.A Visual Gear Box Condition	OIL LEAK,OIL SUMB DENT	حالة الجير النظري
08.B Road Test	NOT CHECK	فحص علي الطريق
09 Chassis Condition		الشاصي
09.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
10 Brake Condition		الفرامل
10.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
11 Suspension System		ممتص الصدمات
11.A Arms	LOWER ARM ,UPPER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.