



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	21 Jun 2022, 16:00:52
Transaction Number	20620662 (CC10006)	Queue Number	312309



Chassis Number	WBAFE81079L094265
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	X5
Model Year	2009
Color	Grey
Mileage	141307 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.B Trunk	PORTION REPAIRED,REPAINTED, AUTO SWITCH RUBBER MISSING	صندوق
01.C Fenders	FRONT FIBER PAINT CANOT CHECK	مدكار
01.D Floor	UNER FLOOR FULLY COVERED CHECKED VISIBLE AREA	الارضية
01.E Doors	FRONT LEFT SIDE PORTION REPAINTED	أبواب
02 Engine Condition		المحرك
02.A Smoke	MINOR WHITE SMOKE	دخان
02.B Mount	MOUNT RUBBER CRACKED	كرسي
02.C Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظري
03 Interior Condition		الحاله الداخليه
03.A Mirror	LEFT SIDE FOLDING & BOTH SIDE ADJUSTMENT NOT WORKING	المرآيا
03.B Roof Ceiling	LOOSE	بطانه السقف
03.C Door Panel	PORTION LOOSE	لوحة بطانة الباب
03.D Other	CENTER CUP CONSOLE BOX COVER MISSING	اخرى

DEFECT	REMARKS	
03.E Audio	LCD FADED	صوتيات
03.F AC Condition	OK	المكيف
03.G Power Window Switch	REAR RIGHT SIDE NOT WORKING OWN SWITCH	مفتاح النافذه
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	OIL LEAK REFITTED	حالة الجير النظرى
04.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
05 Suspension System		ممتص الصدمات
05.A Arms	LOWER ARM & CONTROL ARM BUSHES CRACKED	ازرع
05.B Other	STABILIZER LINK BOOT CUT	اخرى
05.C Ball Joint	BOOT CUT	مفصل كروي
06 Chassis Condition		الشاسي
06.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
07 Steering Condition		المقود
07.A Axle	LEAK	اكسلات
07.B Tie Rod End	BOOT CUT	مؤخرة الرودادت
07.C Steering Oil	OIL LEAK	زيت المقود
08 Tires and Rims Condition		الاطارات
08.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
08.B Front Tyre	BOTH SIDE 2021	الاطار الامامي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.