CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3016254
Transaction Date	23 Nov 2026, 16:45:58
Site Name	840 - Emirates Auctions
Transaction Number	11237595 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WDDYJ8AA1L*******
Specification	Imported
Make	Mercedes
Model	AMG GT
Model Year	2020
Color	Blue
Mileage	40241 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECK,REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES(BODY KIT MODIFIED)	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERED MINOR DENT	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	FIBER PAINT NOT CHECK,REFITTED	غطاء المحرك
01.G Trunk	REFITTED,STAY SHOCK NOT WORKING	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME RADIATOR SUPPORT BULK HEAD INNER FENDER FRAME REPAIRED ASSEMLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED DENT / OUTER SUPPORT BRACKET DAMAGED CRACK	الشاسيه
02.B Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED , OIL LEAK , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	CRACK	حالة المقاعد
05 Exhaust System		نظام العادم

Condition	Remarks	الحالة
05.A Other	CUT REWELDED , SYSTEM MODIFIED	اخري
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07.C Rims Condition	DENT SCRATCHES / HUB COVER MISSING	حالة الجنوط
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
09.B Other	SUSPENSION PARTS REFITTED	اخري
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY,CUP HOLDER SLIDING COVER STUCK	اخري
10.B AC Condition	NOT WORKING	المكيف
10.C Dash Board	LEATHER REPLACED ,CLUSTER FRAME DETACHED	لوحة القياده
10.D Door Panel	PORTION DAMAGED	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae