

Queue Number

2881134

Transaction Date

17 Oct 2026, 11:17:57

Site Name

840 - Emirates Auctions

Transaction Number

55346358 (CC10009) (CC10012)



Vehicle Details

Chassis Number

SALWR2VF4E*****

Specification

Imported

Make

Range Rover

Model

Sport

Model Year

2014

Color

Black

Mileage

153011 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders

FRONT LEFT SIDE REPAINTED PORTION REPAIRED

مدكار

01.B Paint

BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES

الصبغ

01.C Doors

FRONT LEFT SIDE REPAINTED

أبواب

01.D Rusty

UNDER BODY PARTS GETTING RUSTY

صدأ

01.E Floor

FLOOR CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY

الارضية

01.F Bumper

MISALIGN , PORTION CRACK

دعامية

01.G Sign of front accident

FRONT BUMPER BULK HEAD ASSEMBLY REFITTED

وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis

CHECKED VISIBLE AREA OK

الشاسيه

02.B Chassis Number

VIN LAMINATED, CHECKED ON STICKER

رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition

OIL WET OPEN REFITTED GETTING RUSTY

الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition

DRIVER SEAT PORTION CUT

حالة المقاعد

05 Transmission Condition

الجير

05.A Gear Box Visual Condition

REFITTED, BOLTS LOOSE, GETTING RUSTY

الحالة النظرية للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE BRACKET PORTION DAMAGED	الاضاءة الرئيسية
07.B Tail Light	PORTION FADED	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Hand Brake	SWITCH DAMAGED	فرامل اليد
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY , CENTER CONSOLE BOX BUTTON PORTION FADED	اخرى
09.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING PROPERLY , LEFT SIDE FOLDING NOT WORKING , LOOSE	المرآيا
09.C AC Condition	OK	المكيف
09.D Roof Ceiling	REFITTED , PORTION LOOSE	بطانة السقف
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	LOOSE	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae