



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>28 Sep 2022, 17:56:59</b>
Transaction Number	<b>72564342 (CC10006)</b>	Queue Number	<b>597603</b>



Chassis Number	<b>55SWF4JB9GU154958</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>C 300</b>
Model Year	<b>2016</b>
Color	<b>Grey</b>
Mileage	<b>232401 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Lights</b>		<b>الاضاءة</b>
01.A Warning Light	WARNING LIGHTS ON IN DISPLAY	ضوء تحذير
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02.B Floor	UNDER FLOOR COVERED ,CHECKED ONLY VISIBLE AREA.	الارضية
02.C Sign of front accident		وجود مؤشر لحادث في المقدمة
02.D Sign of back accident		وجود مؤشر لحادث في الخلف
02.E Sign of side accident		وجود مؤشر لحادث في الجانب
02.F Bumper	FRONT BUMPER LEFT BRACKET REPAIRED ,MINOR DENT TRUNK GALLERY DENT .	دعامية
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Visual Gear Box Condition	OK	حالة الجير النظري
03.B Road Test	NOT CHECKED.	فحص علي الطريق
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A Roof Ceiling	PORTION LOOSE	بطانه السقف

DEFECT	REMARKS	
04.B AC Condition	OK	المكيف
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	OK	حالة المحرك النظري
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2020,WORN OUT.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020,WORNOUT.	الاطار الخلفي
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.