



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Oct 2021, 14:46:31
Transaction Number	83682698 (CC10006)	Queue Number	312309



Chassis Number	WP1ZZZ9PZ8LA36370
Engine Number	
Vehicle Class	Car
Manufacturer	Porsche
Model	Cayenne
Model Year	2008
Color	Grey
Mileage	274452 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED	الصبغ
01.B Fenders	FRONT BOTH SIDE & REAR RIGHT FENDER REPAINTED	مدكار
01.C Doors	RIGHT BOTH SIDE DOOR REPAINTED	أبواب
01.D Bonnet	REPAINTED	غطاء المحرك
01.E Trunk	REPAINTED, PORTION REPAIRED	صندوق
01.F Roof	PORTION REPAINTED, PAINT FADED	السقف
01.G Bumper	REPAINTED	دعامية
02 Lights		الاضاءة
02.A Warning Light	WARNING ON IN DISPLAY	ضوء تحذير
02.B Head Light	OK	الاضاءة الرئيسية
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Propeller Shaft	PROPELLER SHAFT FLANGE RUBBER CRACKED	ناقل الحركة
03.C Gear Box	OIL LEAK	الجير
03.D Gear Box Mount	MOUNT BUSHES CRACKED	كرسي الجير
04 Suspension System		ممتص الصدمات

DEFECT	REMARKS	
04.A Shock Absorber	4WD & HYDRUALIC SYSTEM SWITCH NOT WORKING	ممتص الصدمات
04.B Suspension Subframe	REAR SUSPENSION SUB FRAME MOUNT BUSHES CRACKED	
04.C Ball Joint	LEFT LOWER BALL JOINT HAVE EXTRA NUT	مفصل كروي
05 Interior Condition		الحاله الداخليه
05.A Mirror	LEFT FOLDING NOT WORKING	المرايا
05.B Roof Light	NOT WORKING	أنارة السقف
05.C AC Condition	OK	المكيف
06 Engine Condition		المحرك
06.A Engine Condition	OIL LEAK	حالة المحرك
07 Steering Condition		المقود
07.A Axel	REAR AXLE BOOT CUT	اكسلات
07.B Steering Boot	BOOT CUT	ربلة المقود
08 Chassis Condition		الشاسي
08.A Chassis	OK	الشاسيه
09 Tires and Rims Condition		الاطارات
09.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
09.B Rear Tyre	BOTH 2020,2021	الاطار الخلفي
09.C Rims Condition	HAVE SCRATCHES	حالة الجنوط
10 Wipers and Arms		المساحات
10.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.