

Queue Number 2811084

Transaction Date 28 Sep 2026, 16:55:25

Site Name
840 - Emirates AuctionsTransaction Number
21042906 (CC10010) (CC10011)

Vehicle Details

Chassis Number	WDB2093761*****
Specification	Imported
Make	Mercedes
Model	CLK 55 AMG
Model Year	2004
Color	Silver
Mileage	170199 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	FRONT RIGHT SIDE & REAR LEFT SIDE REPAINTED , FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED , MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS RUSTY.	صدأ
01.D Floor	UNDER BODY FULLY COVERED CHECK VISIBLE AREA ONLY,	الارضية
01.E Bumper	MISALIGN , SCRATCHES	دعامية
01.F Windshield	FRONT GLASS SPOT DENT	زجاج
01.G Trunk	REFITTED , REPAINTED	صندوق
01.H Vehicle Year Model	2003	سنة صنع المركبة

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COVERED MUDDY CHECK VIISBLE AREA ONLY / OK.	الشاسيه
02.B Chassis Number	FOR PROPERLY INSPECTION NEED TO REMOVE FENDER COVER UNDER COVER.	رقم القاعدة

03 Engine Condition المحرك

03.A Engine Visual Condition	REFITTED ,OIL LEAK ,COMPONENT PARTS RUSTY.	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	FRONT LEFT SIDE SEAT SIDE PANEL DAMAGE , PORTION CRACK	حالة المقاعد
---------------------	--	--------------

05 Transmission Condition الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED ,OIL WET COMPONENT PARTS RUSTY GET JERKING.	الحالة النظرية للجير
05.B Gear Box Mount	LOWER SIDE ONE MOUNT BOLT MISSING.	كرسي الجير
05.C Propeller Shaft	FLANGE BUSHES CRACKED.	ناقل الحركة
05.D Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2024 BOTH SIDE	الاطار الامامي
06.B Rear Tyre	2025 BOTH SIDE	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	BOTH SIDE UPPER RUBBER PANEL MELTED DAMAGE	الاضاءة الرئيسية
07.B Tail Light	BOTH SIGN OF CRACK	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
08.B Hand Brake	WEAK.	فرامل اليد
09 Suspension System		ممتص الصدمات
09.A Other	SUSPENSION PARTS REFITTED.	اخرى
09.B Stabilizer Bar And Link Rod	REAR STABILITY SENSOR LINKAGE MISSING.	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Axle	REAR AXLE BOOT CUT ,GREASE LEAKING.	اكسلات
11 Interior Condition		الحالة الداخليه
11.A Other	CENTER CONSOLE BOX COVER WORN OUT/INTERIOR PARTS GETTING RUSTY.	اخرى
11.B Mirror	BOTH SIDE VIEW MIRROR REFLECTOR HOUSING SIGN OF SCRATCHES / LEFT SIDE GLASS GETTING FADED	المرآيا
11.C AC Condition	OK	المكيف
11.D Dash Board	PORTION WORN OUT	لوحة القيادة
11.E Roof Ceiling	PORTION LOOSE	بطانه السقف
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae