

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 57881761 (CC10006) Transaction Date

Queue Number

02 Mar 2023, 14:55:29

681381

Chassis Number

mber WDC0G4GB2JF321279

Engine Number Vehicle Class

Car

Manufacturer

Mercedes

Model

Model Year

GLC 250

2018

Color

Black

Mileage

74066 Km

Fuel Type

Petrol

таот туро

_

Specification

No. Of Cylinders

GCC Specification

DEFECT REMARKS

01 Interior Condition		الحاله الداخليه
01.A AC Condition	ОК	المكيف
O2 Body		جسم المركبة
02.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار

02.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
02.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR SCRATCHES	الصبغ
02.C Doors	REAR LEFT SIDE PORTION REPAINTED	أبواب
02.D Floor	UNDER BODY COVERD CHECKED VISIBLE AREA ONLY	الارضية
02.E Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ

03 Tires and Rims Condition	الاطارات
-----------------------------	----------

03.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي

04 Transmission Condition

04.A Visual Gear Box	ОК	حالة الجير النظرى
Condition		

05 Chassis Condition

DEFECT	REMARKS	
05.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
06 Engine Condition		المحرك
06.A Visual Engine Condition	ОК	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير سارى.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.