

## **TEST CERTIFICATE**

Site Number
Transaction Number

840-Emirates Auctions 22940923 (CC10006) Transaction Date

01 Jul 2022, 12:04:39

Queue Number 312309

Chassis Number

WVGBF2CA7KC523679

Engine Number

Vehicle Class Car

Manufacturer Volkswagen

Model Teramont

Model Year

2019

Color

Grey

Mileage

53672 Km

Fuel Type

Petrol

No. Of Cylinders

4

Specification

**GCC Specification** 

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
02 Transmission Condition		الجير
02.A Visual Gear Box Condition	ОК	حالة الجير النظرى
02.B Road Test	NOT CHECK	فحص علي الطريق
03 Engine Condition		المحرك
03.A Visual Engine Condition	OK	حالة المحرك النظرى
04 Chassis Condition		الشاصي
04.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
05 Body		جسم المركبة
O5.A Floor	UNDER FLOOR CHASSIS FULLY COVERED, CHECKED VISIBLE AREA OK	الارضية
05.B Fenders	REAR RIGHT SIDE PORTION REPAIRED, REPAINTED	مدكار
05.C Doors	REAR RIGHT SIDE PORTION REPAIRED, REPAINTED	أبواب

DEFECT REMARKS

05.D Paint BODY PORTION REPAIRED,REPAINTED & MINOR DENT SCRATCHES

06 Interior Condition

06.A AC Condition

OK

OK

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.