

Queue Number	2244097	Transaction Date	12 Mar 2026, 14:51:46
Site Name	840 - Emirates Auctions	Transaction Number	35574712 (CC10018) (CC10018)



Vehicle Details

Chassis Number	JN6BE6BS0F*****
Specification	GCC Specification
Make	Nissan
Model	Urvan
Model Year	2015
Color	White
Mileage	277018 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		
جسم المركبة		
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.D Sign of back accident	BACK PANEL REPAIRED, DENT	وجود مؤشر لحادث في الخلف
02 Chassis Condition		
الشاسي		
02.A Chassis	CHASSIS MUDDY, GETTING RUSTY, CROSS MEMBER , RUSTY / BULGED	الشاسيه
03 Engine Condition		
المحرك		
03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED, OIL WET, OIL PAN DENT, PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Seats Condition		
المقاعد		
04.A Seat Condition	COVER PORTION DAMAGED, CENTER CONSOLE COVER DAMAGED	حالة المقاعد
05 Transmission Condition		
الجير		
05.A Gear Box Visual Condition	NOT CHECKED, OIL WET, PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		
الاطارات		

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2023, DRY CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020, CRACKED, EXPIRED	الاطار الخلفي
06.C Rims Condition	RUSTY	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED, LEFT SIDE CRACKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Leaf Spring	BUSH CRACKED	مفصل كروي عمود التوازن و مثبت عمود التوازن
09.B Ball Joint	BOOT CUT	
09.C Stabilizer Bar And Link Rod	BOOT CUT	
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
11.B AC Condition	NOT CHECKED	المكيف
11.C Floor Matting	PORTION DAMAGED	فرش الأرضيه
11.D Door Panel	WORN OUT	لوحة بطانة الباب
11.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae