CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3011990
Transaction Date	20 Nov 2026, 16:37:01
Site Name	840 - Emirates Auctions
Transaction Number	18640708 (CC10009) (CC10019)



Vehicle Details

Chassis Number	JNRAZ25Y7B*******
Specification	GCC Specification
Make	Infiniti
Model	QX56
Model Year	2011
Color	White
Mileage	140258 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REPAINTED,PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,SHAPE CHANGE INFINITI TO NISSAN PATROL	الصبغ
01.C Doors	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED,PORTION REPAIRED,FRONT REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS MUDDY PORTION DENT	الارضية
01.F Bonnet	REFITTED,REPAINTED	غطاء المحرك
01.G Other	BODY SHAPE CHANGED	اخري
01.H Trunk	REFITTED ,REAR SWITCH NOT WORKING	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME BULK HEAD ASSEMBLY REFITTED MODIFIED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSISCOMPLETELY MUDDY PORTION GETTING RUSTY /OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK OPEN REFITTED GETTING RUSTY SHAKING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد
05 Exhaust System		نظام العادم

Condition	Remarks	الحالة
05.A Other	CUT REWELDED	اخري
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	OPEN REFITTED JERKING GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CUT	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحاله الداخليه
09.A Other	INETRIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
09.B Mirror	LEFT SIDE FOLDING NOT WORKING & CENTER MIRROR PORTION LOOSE	المرايا
09.C AC Condition	OK	المكيف
09.D Audio	SCREEN PORTION FADED	صوتيات
09.E Dash Board	PORTION CRACKED MELTED	لوحة القياده
09.F Door Panel	PORTION CRACKED	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae