



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Nov 2021, 18:03:15
Transaction Number	33481183 (CC10006)	Queue Number	312309



Chassis Number	JN8AY2NYOF9120445
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2015
Color	--
Mileage	286759 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
02 Body		جسم المركبة
02.A Fenders	REAR BOTH SIDE & FRONT LEFT SIDE REPAIRED, REPAINTED	مذكار
02.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
02.C Bumper	REPAINTED	دعامية
02.D Trunk	PORTION REPAIRED & REPAINTED	صندوق
02.E Rusty	UNDER BODY PARTS , CHASSIS , SUSPENTION GETTING RUSTY	صدأ
02.F Door Handle & Lock	HANDLE TRUNK MISSING	مقابض الأبواب والأقفال
03 Interior Condition		الحالة الداخليه
03.A AC Condition	OK & REAR RIGHT SIDE GRAIL MISSING	المكيف
03.B Mirror	OK	المرايا
03.C Door Panel	PORTION CRACKED & SCRATCHES	لوحة بطانة الباب
03.D Steering Wheel and	COVER WORN OUT	عجلة القيادة وازرار التحكم

DEFECT	REMARKS	
control buttons		
04 Engine Condition		المحرك
04.A Engine Condition	OK	حالة المحرك
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Gear Box	OK	الجير
06 Lights		الاضاءة
06.A Head Light	OK	الاضاءة الرئيسية
06.B Other	OK	اخرى
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
08 Seats Condition		المقاعد
08.A Other	SEAT COVER DIRTY	اخرى
09 Chassis Condition		الشاصي
09.A Chassis	CHASSIS FRAME GETTING RUSTY	الشاسيه
10 Wipers and Arms		المساحات
10.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
11 Steering Condition		المقود
11.A Axel	LEFT SIDE BOOT CUT	اكسلات
12 Suspension System		ممتص الصدمات
12.A Shock Absorber	REAR LEFT SIDE LEAK	ممتص الصدمات
12.B Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.