



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>25 Jan 2023, 16:55:39</b>
Transaction Number	<b>53635590 (CC10009)</b>	Queue Number	<b>663985</b>



Chassis Number	<b>2C3CDZAG0KH557656</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Dodge</b>
Model	<b>Challenger</b>
Model Year	<b>2019</b>
Color	<b>Black</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	NOT CHECKED	المكيف
01.B Odometer reading	NOT CHECKED	قراءة عداد المسافات
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Floor	FLOOR DENT	الارضية
02.B Paint	BODY PORTION REPAINTED,PORION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02.C Bumper	PORTION DAMAGED	دعامية
02.D Sign of back accident		وجود مؤشر لحادث في الخلف
02.E Trunk	TRUNK NOT OPEN	صندوق
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING	حالة المحرك النظرى
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Road Test	NOT CHECKED	فحص علي الطريق
04.B Visual Gear Box Condition	NOT CHECKED	حالة الجير النظرى

DEFECT	REMARKS	
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH SIDE 2017/2020 EXPIRED,CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2019/2018 CRACKED	الاطار الخلفي
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	REAR LEFT SIDE EXTENSION OUTER MINOR DENT	الشاسيه
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Arms	LOWER ARM BUSHES CUT	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Tie Rod End	BOOT CUT	مؤخرة الروداد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.