



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>25 May 2023, 12:06:48</b>
Transaction Number	<b>73746813 (CC10013)</b>	Queue Number	<b>726275</b>



Chassis Number	<b>JTDBW23E260105769</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Corolla</b>
Model Year	<b>2006</b>
Color	<b>White</b>
Mileage	<b>280494 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	NOT WORKING	المكيف
01.B Other	INTERIOR CONDITION DIRTY	اخرى
01.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	MINOR OIL LEAK SHAKING	حالة المحرك النظرى
02.B Smoke	BLACK	دخان
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Other	VISUAL TEST ONLY	اخرى
03.B Bumper	MISALIGN PORTION CRACK	دعامية
03.C Paint	BODY PORTION REPAINTED PORTION REPAIRED PORTION GETTING RUSTY & FADED MINOR DENT SCRATCHES	الصبغ
03.D Floor	UNDER FLOOR CHASSIS SUSPENSION PARTS NOT CHECK	الارضية
<b>04 Brake Condition</b>		<b>الفرامل</b>
04.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
<b>05 Lights</b>		<b>الاضاءة</b>

DEFECT	REMARKS	
05.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
<b>06 Seats Condition</b>		<b>المقاعد</b>
06.A Seat Condition	ALL EXTRA COVER	حالة المقاعد
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	NOT CHECK	الشاسيه
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Rear Tyre	CRACKED DAMAGED EXPIRED	الاطار الخلفي
08.B Front Tyre	CRACKED DAMAGED EXPIRED	الاطار الامامي
<b>09 Transmission Condition</b>		<b>الجير</b>
09.A Visual Gear Box Condition	NOT CHECK	حالة الجير النظرى
09.B Road Test	NOT CHECK	فحص علي الطريق

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.