CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934093
Transaction Date	03 Nov 2026, 12:50:19
Site Name	840 - Emirates Auctions
Transaction Number	61300776 (CC10010) (CC10010)



Vehicle Details

Chassis Number	MDHBN7AD8D*******
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2013
Color	White
Mileage	321928 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REFITTED REPAINTED REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED , FRONT REFITTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.G Windshield	FRONT CRACKED .	زجاج
01.H Bonnet	REFITTED REPAINTED	غطاء المحرك
01.I Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS END BEND, REAR EXTENSION END KINK CRASH BOX DAMAGED.	الشاسيه
03 Engine Condition		**المحرك**
03.A Smoke	WHITE .	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
06 Lights		الاضاءة
06.A Tail Light	LOOSE. MISALIGN .	الضوء الخلفي
06.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY.	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B AC Condition	NOT COOLING.	المكيف
10.C Door Panel	WORN OUT PORTION LOOS.E	لوحة بطانة الباب
10.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.E Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.