CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2963007
Transaction Date	09 Nov 2026, 16:32:52
Site Name	840 - Emirates Auctions
Transaction Number	59427983 (CC10009) (CC10011)



Vehicle Details

Chassis Number	WDCDA5GB8F*******
Specification	GCC Specification
Make	Mercedes
Model	ML 400
Model Year	2015
Color	White
Mileage	121472 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REFITTED	مدكار
01.B Paint	BODY TOTALLY STICKER PAINT NOT CHECK,STICKER PORTION DAMAGED LOOSE	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSISCOVERED COMPLETELY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.E Bumper	MISALIGN,LEFT SIDE REFLECTOR DAMAGED,RIGHT PORTION LOOSE	دعامية
01.F Bonnet	STAY SHOCK NOT WORKING	غطاء المحرك
01.G Trunk	LUGGAGE SHADE MISSING	صندوق
01.H Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR OIL LEAK REFITTED, HOLE COVER MISSING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION CRACK WORN OUT,FRONT RIGHT SIDE PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL WET REFITTED MINOR JERKING	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 WORN OUT CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	EXTRA STICKER	الاضاءة الرئيسية
07.B Tail Light	EXTRA STICKER,LEFT SIDE PORTION DAMAGED	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08.B Hand Brake	SWITCH FADED	فرامل اليد
09 Suspension System		ممتص الصدمات
09.A Other	SUSPENSION REFITTED	اخري
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER,PANEL PORTION DAMAGED PART MISSING,MELTED	اخري
10.B AC Condition	OK,GRILL PORTION DAMAGED,SWITCH PANEL GETTING FADED	المكيف
10.C Power Window Switch And Glass	SWITCH PORTION WORN OUT,REAR BOTH SIDE CURTAIN PORTION DAMAGED	مفتاح النافذه و الزجاج
10.D Dash Board	GLOVE BOX COVER PORTION DAMAGED LOOSE	لوحة القياده
10.E Roof Ceiling	PORTION MINOR LOOSE	بطانه السقف
10.F Sun Visor	LEFT SIDE MIRROR COVER LOOSE LOCK DAMAGED	حاجب الشمس
10.G Door Panel	PORTION MINOR CRACK WORN OUT LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT LOGO MISSING,HORN NOT WORKING	عجلة القيادة وازرار التحكم
10.I Engine Start Button	SMART KEY MISSING	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.