CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2915208
Transaction Date	28 Oct 2026, 15:01:11
Site Name	840 - Emirates Auctions
Transaction Number	42415372 (CC10010) (CC10011)



Vehicle Details

Chassis Number	MMM156FB4H*******
Specification	GCC Specification
Make	Chevrolet
Model	Trailblazer
Model Year	2017
Color	Blue
Mileage	258702 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.G Trunk	REPAIRED REPAINTED	صندوق
01.H Sign of back accident	BUMPER FRAME ,BACK PANEL REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME GETTING RUSTY ,PORTION DENT ,PORTION MUDDY.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER.	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY.	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CRACKED.	ربلة المقود
09.B Steering Box	OIL LEAK.	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B Mirror	LEFT SIDE ASSEMBLY DAMAGED	المرايا
10.C AC Condition	NOT COOLING.	المكيف
10.D Power Window Switch And Glass	REAR BOTH SIDE NOT WORKING ,MAIN SWITCH FADED.	مفتاح النافذه و الزجاج
10.E Roof Ceiling	LOOSE.	بطانه السقف
10.F Sun Visor	LOOSE	حاجب الشمس
10.G Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae