

Queue Number 2855923

Transaction Date 10 Oct 2026, 12:46:03

Site Name
840 - Emirates AuctionsTransaction Number
83725839 (CC10009) (CC10012)

Vehicle Details

Chassis Number	JN8AR05Y42*****
Specification	GCC Specification
Make	Nissan
Model	Pathfinder
Model Year	2002
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS SUSPENSION CHASSIS RUSTY	صدأ
01.D Floor	FLOOR CHASSIS NOT VISIBLE COMPLETELY THICK RUST PROOFED	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Windshield	FRONT CRACKED	زجاج
01.G Bonnet	REFITTED	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY THICK RUST PROOFED, PORTION RUSTY BULGED MUDDY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED, OIL LEAK REFITTED RUSTY MUDDY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED , REAR SEAT MISSING	حالة المقاعد
---------------------	-------------------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED OIL LEAK REFITTED GETTING RUSTY MUDDY	الحالة النظرية للجير
--------------------------------	---	----------------------

Condition	Remarks	الحالة
05.B DIFFERENTIAL	OIL LEAK	الدفرنشل
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025 CRACK	الاطار الخلفي
06.C Rims Condition	HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07.B Indicator & Hazard light	FRONT RIGHT SIDE CRACK	الاشارات
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Other	SUSPENSION GETTING RUSTY	اخرى
08.C Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Steering Oil	OIL LEAK	زيت المقود
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	NOT CHECK , GRILL PORTION DAMAGED	المكيف
10.C Dash Board	PORTION DAMAGED	لوحة القيادة
10.D Door Panel	PORTION DAMAGED	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carscheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carscheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae