



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	06 Oct 2021, 17:49:04
Transaction Number	74510349 (CC10006)	Queue Number	312309



Chassis Number	SALLSAAE4AA249375
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Sport
Model Year	2010
Color	Black
Mileage	105177 N/A

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Head Light	RIGHT LOW & HIGH BEAM NOT WORKING	الاضاءة الرئيسية
01.B Warning Light	WARNING ON IN DISPLAY, SUSPENSION FAULT	ضوء تحذير
01.C Indicator	FRONT RIGHT NOT WORKING	الاشارات
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH 2020	الاطار الامامي
02.B Rear Tyre	BOTH 2020	الاطار الخلفي
03 Seats Condition		المقاعد
03.A Other	OK	اخرى
04 Body		جسم المركبة
04.A Paint	BODY PORTION REPAINTED, REPAIRED	الصبغ
04.B Doors	FRONT RIGHT DOOR REPAIRED, REPAINTED	أبواب
05 Engine Condition		المحرك
05.A Other	OIL LEAK & MISFIRING	اخرى
06 Transmission Condition		الجير
06.A Gear Box	OIL LEAK	الجير
07 Suspension System		ممتص الصدمات
07.A Arms	REAR LOWER ARM BUSHES CRACKED	ازرع

DEFECT	REMARKS	
08 Chassis Condition		الشاسي
08.A Chassis	OK	الشاسيه
09 Interior Condition		الاجزاء الداخلية
09.A AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.