



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 May 2022, 16:50:22</b>
Transaction Number	<b>17809533 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>3GCPK9E7XCG208633</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Silverado</b>
Model Year	<b>2012</b>
Color	<b>Grey</b>
Mileage	<b>419371 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	MINOR OIL LEAK & REFITTED	حالة الجير النظرى
<b>02 Seats Condition</b>		<b>المقاعد</b>
02.A Seat Condition	FRONT RIGHT SIDE SEAT ADJUSTMENT HANDLE MISSING	حالة المقاعد
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Paint	BODY TOTALY REPAINTED,PORTION REPAIRED , MINOR DENTS, SCRATCHES	الصبغ
03.B Rusty	UNDER BODY PARTS & SUSPENTION, FLOOR, CHASSIS GETTING RUSTY	صدأ
03.C Door Handle &Lock	FRONT LEFT SIDE INNER DOOR HANDLE DAMAGED & CENTER LOCK BUTTON DAMAGED	مقابض الأبواب والأقفال
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Fog light	LENS FADED & NOT WORKING	كشاف الضباب
04.B Head Light	LOOSE & LEFT SIDE LENS FADED	الاضاءة الرئيسية
04.C Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

DEFECT	REMARKS	
<b>05 Interior Condition</b>		<b>الحاله الداخليه</b>
05.A AC Condition	OK	المكيف
05.B Other	CENTER CONSOLE BOX PORTION DAMAGED	اخرى
05.C Mirror	ADJUSTMENT NOT WORKING	المرايا
05.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
05.E Dash Board	PORTION CRACKED	لوحة القيادة
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Rear Tyre	BOTH SIDE 2018 & CRACKED	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2018 & CRACKED	الاطار الامامي
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	MINOR OIL LEAK & REFITTED	حالة المحرك النظري
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis Number	CHASSIS NUMBER NOT VISIBLE IN CHASSIS FRAME &NO CHECK ONLY LEFT SIDE DOOR ,WINDSHIELD	رقم القاعدة
08.B Chassis	CHASSIS FRAME RUSTY	الشاسيه
<b>09 Suspension System</b>		<b>ممتص الصدمات</b>
09.A Leaf Spring	BOTH SIDE BUSHES CUT & LEAF GETTING RUSTY	

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤوله عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	--
Chassis No :	3GCPK9E7XCG208633
Vehicle Make :	CHEVROLET
Vehicle Model :	SILVERADO
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Brown
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	419368 Kms.
Origin : Mexico	Model Year : 2012
Gear Type : Automatic	Engine Size : 6600 CC
Engine No : NIL	Horse Power : 319
Axles No : 2	Cylinders : 8
No Of Doors : 4	No Of Seats : 5
G. V. W. : 3600 Kgs.	Empty Weight : 2500 Kgs.

Certificate Number :	5-TAS-2022-16720560
Inspection Date :	09-05-2022
Certificate Print Date :	09-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Qusais
Total Time Taken :	15 min 11 sec
Appointment Ref Number :	--
Start Time : 12:12	End Time : 12:27
Lane : 07	Token No. : 365
Attempt : 2	Prints No : 2

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)

108 KM	12 L	20 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

**Inspection Remarks:** CHASSIS & UNDER BODY COMPONENTS RUSTY. FRONT CHASSIS CROSS MEMBER REPAIRED

## Payment Details

Inspection Performed by 62437	Payment Method Cash	Transaction Number 16720560	Service Fees AED 70 Collected on 09/05/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Muhammad Essa Abdullah Ali AlBalooshi

- 1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- 2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

