

Queue Number

2873911

Transaction Date

16 Oct 2026, 12:27:09

Site Name

840 - Emirates Auctions

Transaction Number

54511636 (CC10010) (CC10010)



Vehicle Details

Chassis Number	3N1AB7AP2H*****
Specification	Imported
Make	Nissan
Model	Sentra
Model Year	2017
Color	Grey
Mileage	143661 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED PORTION REPAINTED.REAR BOTH SIDE REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADE,LEFT SIDE COMPLETE CEMENT.. D	الصبغ
01.C Doors	FRONT BOTH SIDE ,REAR LEFT SIDE REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.E Bonnet	REPAINTED REFITTED .	غطاء المحرك
01.F Pillars	LEFT SIDE PILLAR OUTER PANEL ROCKER PANEL ,WHEEL ARCH REPAIRED.	القوائم
01.G Door Handle &Lock	FRONT LEFT SIDE OUTER HANDLE DAMAGED , RIGHT SIDE LOOSE.	مقابض الأبواب والأقفال
01.H Sign of front accident	BULKHEAD,RADIATOR SUPPORT REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of side accident		وجود مؤشر لحادث في الجانب
01.J Sign of back accident	BACK PANEL DENT.	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS PORTION DENT RUSTY ,REAR EXTENSION COMPLETE THICK RUSTPROOFED NOT VIISBLE .	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACKED.	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY.	دواسة الفرامل
07.B Disc&Drum	PARTS RUSTY.	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK.	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخرى
09.B AC Condition	NORMAL COOLING.	المكيف
09.C Steering Wheel and control buttons	GETTING WORN OUT .	عجلة القيادة وازرار التحكم
09.D Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae