

02.E Rusty

## **TEST CERTIFICATE**

20 Nov 2022, 17:25:36

الصبغ

صدأ

Site Number **840-Emirates Auctions** Transaction Date

46140313 (CC10006) Oueue Number 627074

Transaction Number

Chassis Number **SALCA2BG8GH576309** 

**Discovery** 

**Engine Number** 

Model

Vehicle Class Car

Manufacturer **Land Rover** 

Model Year 2016

Color Black

232369 Km

Mileage Fuel Type **Petrol** 

No. Of Cylinders

Specification **GCC Specification** 

REMARKS DEFECT

**01 Interior Condition** الحاله الداخليه

01.A AC Condition NORMAL COOLING المكيف 01.B Door Panel **COVER LOOSE** لوحة بطانة الباب **PORTION DAMAGED & LOOSE** 01.C Roof Ceiling بطانه السقف

02 Body جسم المركبة

PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON 02.A Paint

**BODY** 

02.B Fenders REAR RIGHT SIDE SKIRT MISSING مدكار

02.C Sign of side accident وجود مؤشر لحادث في الجانب

02.D Sign of back accident وجود مؤشر لحادث في الخلف

**03 Chassis Condition** الشاصي

UNDER BODY PARTS, SUSPENTION GETTING RUSTY

03.A Chassis CHECKED VISIBLE AREA OK الشاسيه

**04 Engine Condition** المحرك

**04.A Visual Engine Condition** SIGN OF LEAK حالة المحرك النظرى

04.B Smoke **BLACK SMOKE** دخان

**BUSH CRACKED** 04.C Mount كرسي

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	ОК	حالة الجير النظرى
06 Steering Condition		المقود
06.A Other	STABILIZER LINK BOOT CUT	اخري
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CUT	ازرع
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2020 WORN OUT, CRACKED	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2020 WORN OUT, CRACKED	الاطار الخلفي
09 Lights		الاضاءة
09.A Head Light	LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
  Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.