CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906040
Transaction Date	29 Oct 2026, 13:24:00
Site Name	840 - Emirates Auctions
Transaction Number	73934130 (CC10010) (CC10011)



Vehicle Details

Chassis Number	MRHGD66346*******
Specification	GCC Specification
Make	Honda
Model	City
Model Year	2006
Color	Silver
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REFITTED ,RIGHT SIDE DAMAGED. .	مدكار
01.B Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.F Bonnet	REFITTED .	غطاء المحرك
01.G Trunk	NOT CLOSSING.	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS REPAIRED DENT & REAR EXTENSION END REPAIRED DENT , GETTING RUSTY.	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2022 CRACKED WORN OUT	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022 CRACKED WORN OUT	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
06.B Tail Light	CRACKED	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B Mirror	LEFT SIDE MISSING	المرايا
10.C AC Condition	NOT CHECKED .	المكيف
10.D Dash Board	LOOSE PORTION DAMAGED .	لوحة القياده
10.E Roof Ceiling	PORTION LOOSE.	بطانه السقف
10.F Sun Visor	LOOSE	حاجب الشمس
10.G Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae