

Queue Number

2899751

Transaction Date

26 Oct 2026, 11:16:47

Site Name

840 - Emirates Auctions

Transaction Number

58931862 (CC10010) (CC10010)



Vehicle Details

Chassis Number

WVWBR7A30C*****

Specification

GCC Specification

Make

Volkswagen

Model

Passat

Model Year

2012

Color

White

Mileage

260515 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

5

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED. & REAR BOTH SIDE REPAIRED REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES ,	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.E Bumper	MISALIGN,SCRATCHES , PORTION DAMAGED.	دعامية
01.F Bonnet	REFITTED ,REPAIRED REPAINTED.	غطاء المحرك
01.G Trunk	REPAINTED REPAIRED.	صندوق
01.H Sign of front accident	FRONT BULKHEAD RADIATOR SUPPORT REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL COMPARTMENT FLOOR QUARTER PANEL REPAIRED.	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /PORTION DENT .	الشاسيه
02.B Other	REMOVE FENDER UNDER COVER FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Lights		الاضاءة
05.A Head Light	LENS FADED.	الاضاءة الرئيسية
05.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
06 Suspension System		ممتص الصدمات
06.A Shock Absorber	LEAK	ممتص الصدمات
06.B Arms	BUSHES CRACKED.	ازرع
07 Steering Condition		المقود
07.A Steering Boot	CUT	ربلة المقود
07.B Steering Box	OIL LEAK .	جهاز المقود
07.C Axle	BOOT CUT	اكسلات
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخرى
08.B AC Condition	NOT COOLING	المكيف
08.C Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
08.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
08.E Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae