CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2998615
Transaction Date	17 Nov 2026, 14:28:33
Site Name	840 - Emirates Auctions
Transaction Number	48073337 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JTEHJ09J06*******
Specification	GCC Specification
Make	Toyota
Model	Land Cruiser
Model Year	2006
Color	White
Mileage	303261 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAIRED REPAINTED,MINOR DENT SCRATCHES,PORTION RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK , FLOOR PORTION RUSTY HOLE	الارضية
01.E Bumper	MINOR DENT	دعامية
01.F Windshield	FRONT SPOT CRACK	زجاج
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	BOTH SIDE C/PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	REFITTED,COMPARTMENT COVER PORTION DAMAGED PART MISSING	صندوق
01.J Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS RUST PROOFED GETTING RUSTY / MIDDLE CROSS MEMBER RUSTY REPAIRED HOLE WEAK	الشاسيه
02.B Chassis Number	VIN AREA RUST PROOFED CHECK VIN PLATE ONLY	رقم القاعدة
03 Engine Condition		المحرك
03.A Mount	MOUNT RUBBER WEAK	كرسي
03.B Engine Visual Condition	REFITTED , ABNORMAL NOISY ,MUDDY , PARTS GETTING RUSTY	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT RIGHT SEAT ADJUSTMENT NOT WORKING HANDLE COVER MISSING,REAR SEATS MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	CUT REWELDED	اخري
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
06.B DIFFERENTIAL	OIL WET	الدفرنشل
06.C Road Test	NOT CHECKED	فحص علي الطريق
06.D Clutch	HARD	القابض
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2023 WORN OUT	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2022,RIGHT 2023 WORN OUT CRACK	الاطار الخلفي
07.C Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
08 Lights		الاضاءة
08.A Head Light	LENS FADED,RIGHT SIDE BRACKET DAMAGED	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	MINOR LEAK	ممتص الصدمات
09.B Arms	ARM BUSHES DRY CRACK	ازرع
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER COOL BOX COVER LOOSE PORTION CRACKED,REAR CUP HOLDER DAMAGED	اخري
10.B AC Condition	FRONT NO COOLING,REAR NOT WORKING SWITCH PANEL LOOSE PORTION DAMAGED	المكيف
10.C Power Window Switch And Glass	MAIN SWITCH PANEL LOOSE,REAR RIGHT SIDE SWITCH NOT WORKING PROPERLY	مفتاح النافذه و الزجاج
10.D Dash Board	GLOVE BOX DAMAGED	لوحة القياده
10.E Roof Ceiling	PORTION DAMAGED LOOSE	بطانه السقف
10.F Door Panel	PORTION DAMAGED WORN OUT	لوحة بطانة الباب
11 Battery Condition		حالة البطارية
11.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**