



Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	: 0
Transaction Number	: 20395706	Plate Category	: PRIVATE
Transaction Date	: 28 JUL 2020 15:45:46	Plate Number	: 7695 EA
Queue Number	: 201746	Import Doc. Ref.	:
Chassis Number	: KMHCS41UBEU567695	Manufacturer/Model	: HYUNDAI/ACCENT
Engine Number	:	Model Year	: 2014
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION	Mileage	: 44779

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		ALL TYRES CRACKED WEAK 2017.
05 Body		الهيكل
05.01 - Rusty		الصدأ
		UNDER FLOOR SUSPENSION PARTS RUSTY.
05.02 - Paint		الصبغ
		BODY BUMPERS MINOR DENTS SCRATCHES.
05.05 - Bumpers		الدعامية
		BOTH BUMPERS,FRONT FENDERS,BONNET REFITTED.
05.06 - Roof		السقف
		ROOF TOP BLACK PAINTED.
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
		FRONT CHANGED.
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok	OK	الشاصي جيد
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.11 - Gear Box Oil Leaking		تهريب زيت الجير
09.25 - Body Repainted		أثر صبغ في المركبة
		BONNET REPAINTED.

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
تسجيل غير مسئولة عن العيوب الخفية