CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906122
Transaction Date	26 Oct 2026, 12:56:10
Site Name	840 - Emirates Auctions
Transaction Number	74787119 (CC10021) (CC10021)



Vehicle Details

Chassis Number	1HGCR2621D*******
Specification	GCC Specification
Make	Honda
Model	Accord
Model Year	2013
Color	White
Mileage	369197 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.C Doors	REAR RIGHT SIDE DOOR REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.F Bumper	MISALIGN	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY , PORTION DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	NO CONTINUE STARTING , ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DAMAGE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2025 & RIGHT SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 & RIGHT SIDE DAMAGE	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CRACK	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY	اخري
10.B Mirror	LEFT SIDE VIEW MIRROR DAMAGE	المرايا
10.C AC Condition	NOT CHECK	المكيف
10.D Dash Board	PORTION WORN OUT	لوحة القياده
10.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.F Sun Visor	LEFT SIDE LOOSE	حاجب الشمس
10.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.H Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae