

Queue Number 2862447

Transaction Date 13 Oct 2026, 16:19:03

Site Name
840 - Emirates AuctionsTransaction Number
45216409 (CC10013) (CC10011)

Vehicle Details

Chassis Number	JN8AY2NY3R*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2024
Color	Black
Mileage	59670 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	LEFT SIDE BOTH REPAINTED PORTION REPAIRED,FRONT BOTH REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED,REFITTED	أبواب
01.D Rusty	UNDER PARTS GETTING RUSTY ,SIGN OF WATER EFFECT	صدأ
01.E Floor	UNDER FLOOR BODY MOUNT REFITTED , RUST PROOFED , MUDDY DIRTY	الارضية
01.F Bumper	MINOR SCRATCHES MISALIGN	دعامية
01.G Windshield	FRONT FULL TINT	زجاج
01.H Bonnet	REPAINTED,REFITTED	غطاء المحرك
01.I Pillars	LEFT SIDE A / B/ PILLAR ROCKER PANEL REPAIRED	القوائم
01.J Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD , INNER FENDER FRAME FIREWALL AREA REPAIRED , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS REPLACED VIN NUMBER REPUNCH	الشاسيه
--------------	-------------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--------------------------------	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	FRONT BOTH SIDE SEAT LOOSE, REAR MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST SYSTEM MODIFIED	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
07.C Spare Tire & Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION PARTS REFITTED	اخرى
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	LEFT SIDE LOOSE	المرآيا
09.C AC Condition	LOW COOLING	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae