



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **14 Aug 2022, 10:28:59**  
 Transaction Number **42846345 (CC10008)** Queue Number **312309**



Chassis Number **1FMEU7EE5AUA42418**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Ford**  
 Model **Explorer**  
 Model Year **2010**  
 Color **Brown**  
 Mileage **296496 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Doors	RIGHT SIDE BOTH PORTION REPAIRED,REPAINTED	أبواب
01.B Fenders	RIGHT SIDE BOTH PORTION REPAIRED,REPAINTED & FRONT LEFT SIDE PORTION REPAINTED,FRONT REFITTED	مدكار
01.C Bonnet	PORTION REPAIRED,REPAINTED & REFITTED,SHOCK WEAK	غطاء المحرك
01.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.E Sign of side accident		وجود مؤشر لحادث في الجانب
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	OIL LEAK REFITTED, SHAKING	حالة المحرك النظري
03.B Mount	MOUNT RUBBER CUT	كرسي
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
04.B Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
04.C Visual Gear Box Condition	OIL LEAK REFITTED, JERKING	حالة الجير النظري
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Arms	BUSHES CUT	ازرع
05.B Ball Joint	BOOT CUT	مفصل كروي
05.C Shock Absorber	LEAK	ممتص الصدمات
<b>06 Steering Condition</b>		<b>المقود</b>
06.A Steering Oil	OIL LEAK	زيت المقود
06.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
06.C Steering Boot	BOOT CUT	ربلة المقود
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	CHASSIS FRAME THICK RUST PROOFED OK	الشاسيه
07.B Chassis Number	CLEAN VIN PUNCHING NUMBER AREA FOR RECHECK	رقم القاعدة
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
<b>09 Brake Condition</b>		<b>الفرامل</b>
09.A Brake Pedal	SPONGY	دواسة الفرامل
<b>10 Interior Condition</b>		<b>الحاله الداخليه</b>
10.A AC Condition	OK	المكيف
10.B Sun Visor	COVER LOOSE	حاجب الشمس

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Transfer Certificate :	62448875
Chassis No :	1FMEU7EE5AUA42418
Vehicle Make :	FORD
Vehicle Model :	EXPLORER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Brown
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	296500 Kms.
Origin : United States	Model Year : 2010
Gear Type : Automatic	Engine Size : 4000 CC
Engine No : AUA42418	Horse 210
Axles No : 2	Power :
No Of 5	Cylinders : 6
Doors :	No Of Seats : 7
G. V. W. : 2800 Kgs.	Empty 2054 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17419884		
Inspection Date :	16-08-2022		
Certificate Print Date :	17-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	10 min 15 sec		
Appointment Ref Number :	--		
Start Time :	12:50	End Time :	13:00
Lane :	03	Token No. :	160
Attempt :	1	Prints No. :	1

## Carbon footprint



Keep protecting Dubai environment

## Estimated Vehicle Consumption (Rate last 12 Months)

21342 KM	2197 L	7163 AED	5.3 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 24 %	Service brake imbalance on rear axle 9 %	Parking brake imbalance between LHS and RHS 28 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 4 PPM VOL			

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	4000	3500	

Inspection Remarks: CHASSIS RUST PROOFED

## Payment Details

Inspection Performed by 30544 3104 3104	Payment Method Cash	Transaction Number 17419884	Service Fees AED 170 Collected on 17/08/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

