

Queue Number 2822991

Transaction Date 02 Oct 2026, 11:50:53

Site Name
840 - Emirates AuctionsTransaction Number
40100442 (CC10009) (CC10012)

Vehicle Details

Chassis Number	LMGAC1G88*****
Specification	GCC Specification
Make	GAC
Model	GS4
Model Year	2019
Color	Maroon
Mileage	118661 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE , REAR LEFT SIDE REPAINTED PORTION REPAIRED , FRONT LEFT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DEN SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR RUST PROOFED, PORTION DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Trunk	REPAINTED PORTION REPAIRED	صندوق
01.H Sign of front accident	FRON RIGHT SIDE BULK HEAD, LOWER BRACKET BEND	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY OK	الشاسيه
02.B Chassis Number	LMGAC1G88K1515381	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK PARTS REFITTED, MINOR SHAKING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	OIL WET PARTS REFITTED, MINOR JERKING	الحالة النظرية للجير
--------------------------------	---------------------------------------	----------------------

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025 WORN OUT	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	LEFT SIDE BLADE MISSING	ازرع المساحات والشفرة
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08 Interior Condition		الحالة الداخليه
08.A AC Condition	OK	المكيف
08.B Sun Visor	BOTH SIDE MIRROR LIGHT NOT WORKING	حاجب الشمس
08.C Steering Wheel and control buttons	EXTRA COVER	عجلة القيادة وازرار التحكم
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	SIGN OF OIL MIXED	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae