

Test Certificate




✓ PASS

| | |
|--------------------------|-------------------|
| Transfer Certificate : | 60969448 |
| Chassis No : | JN8FYINY5EX002630 |
| Vehicle Make : | NISSAN |
| Vehicle Model : | PATROL |
| Vehicle Class : | Light Vehicle |
| Body Type : | STATION |
| Fuel : | Benzene |
| Color : | Piege |
| Drive Direction : | -- |
| Dimensions : (H x W x L) | -- x -- x -- |
| Current Odometer : | 186503 kms. |
| Origin : | Japan |
| Gear Type : | Manual |
| Engine No : | TB48 077408 |
| Axles No : | 2 |
| No Of Doors : | 5 |
| G. V. W. : | 2850 Kgs. |
| Model Year : | 2014 |
| Engine Size : | 3500 CC |
| Horse Power : | -- |
| Cylinders : | 6 |
| No Of Seats : | 7 |
| Empty Weight : | 1400 Kgs. |

| | |
|---------------------------|---------------------|
| Certificate Number : | 5-TAS-2022-17262276 |
| Inspection Date : | 24-07-2022 |
| Certificate Print Date : | 24-07-2022 |
| Services : | Registration Test |
| Vehicle Testing Partner : | Tasjeel |
| Vehicle Testing Center : | Tasjeel Al Aweer |
| Total Time Taken : | 14 min 20 sec |
| Appointment Ref Number : | -- |
| Start Time : | 16:11 |
| End Time : | 16:25 |
| Lane : | 02 |
| Attempt : | 2 |
| Token No. : | 217 |
| Prints No. : | 1 |

Carbon footprint



Keep pollutioning Dubai environment

Estimated Vehicle Consumption (Rate last 12 Months)

| | | | |
|-------------------|------------------------|--------------------|---------------------------|
| | | | |
| 24819 KM | 2554 L | 8020 AED | 6.2 ton |
| Distance per year | Fuel consumed per year | Fuel cost per year | Carbon footprint per year |

Inspection Findings

| Discrepancies | Old Value | New Value | Verified |
|--|-----------|--------------|----------|
| Engine Size Discrepancy in Engine Size | 3500 | 4800 | |
| Paint Change Color | Piege | Black , Blue | |
| Vehicle Model - Registration Incorrect Model - Does Not Require Document | PATROL | PATROL | |
| Vehicle Make - Registration Incorrect Make - Does Not Require Document | NISSAN | NISSAN | |

Inspection Remarks:

MINOR ENGINE & STEERING OIL LEAK // REAR CHASSIS BULGED , CHASSIS RUSTY , & RUST PRTOOFED // FENDER BONNET MODIFIED //

Payment Details

| | | | |
|----------------------------------|-----------------------------------|--------------------------------|--|
| Inspection Performed by 30544 | Payment Method Cash | Transaction Number 17262276 | Service Fees AED 70 Collected on 24/07/2022 |
| Parking Slot No -- | Service Name Registration Test | Attempt 2 | Received by Sittu Paloth Sreesan Paloth |

- ① This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only), towards the above service.
 - ② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
- تستخدم هذه الشهادة دليلاً في العمليّات الخاضعة بالترخيص التي لا تُعدّ بهذه الشهادة التي عمليّات أخرى بما في ذلك أعراس البيع أو الشراء طبقاً لعمليّة ترخيص المركبة. لا تتحمل الجهة المصدرة أيّة مسؤولية جراء استعمال هذه الشهادة لغير ما أُعتبرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ المحض.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 01 Aug 2022, 18:18:14 |
| Transaction Number | 59992405 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | JN8FY1NY5EX002630 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Nissan |
| Model | Patrol |
| Model Year | 2014 |
| Color | Black |
| Mileage | 186509 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 6 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|-----------------------------|--|----------------------------|
| 01 Body | | جسم المركبة |
| 01.A Fenders | FRONT REAR FENDER SKIRT MODIFIED | مدكار |
| 01.B Bonnet | BONNET | غطاء المحرك |
| 01.C Other | VEHICLE MODIFIED/ FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED | اخرى |
| 01.D Floor | FLOOR JOINT REPAIRED , STILL DENT | الارضية |
| 01.E Sign of back accident | | وجود مؤشر لحادث في الخلف |
| 01.F Paint | BODY TOTALLY REPAIRED REPAINTED VEHICLE COLOUR CHANGED FROM WHITE TO BLUE | الصبغ |
| 01.G Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 01.H Sign of side accident | | وجود مؤشر لحادث في الجانب |
| 01.I Pillars | BOTH SIDE OUTER PANEL REPAIRED & REPAINTED | القوائم |
| 02 Battery Condition | | حالة البطارية |
| 02.A Battery bracket | MISSING | حامل البطارية |
| 03 Lights | | الاضاءة |
| 03.A Warning Light | WARNING LIGHT ON DISPLAY | ضوء تحذير |
| 03.B Other | ALL LIGHTS MODIFIED | اخرى |

| DEFECT | REMARKS | |
|---|--|----------------------------|
| 04 Interior Condition | | الحاله الداخليه |
| 04.A Steering Wheel and control buttons | HORN NOT WORKING | عجلة القيادة وازرار التحكم |
| 04.B Mirror | RIGHT SIDE MIRROR CRACKED | المرايا |
| 04.C Dash Board | MODIFIED | لوحة القيادة |
| 04.D AC Condition | NOT WORKING | المكيف |
| 04.E Power Window Switch | FRONT RIGHT SIDE NOT WORKING | مفتاح النافذه |
| 05 Seats Condition | | المقاعد |
| 05.A Seat Condition | MODIFIED | حالة المقاعد |
| 06 Tires and Rims Condition | | الاطارات |
| 06.A Rear Tyre | BOTH SIDE 2015 EXPIRE,CRACKED | الاطار الخلفي |
| 06.B Front Tyre | BOTH SIDE 2015 EXPIRE,CRACKED | الاطار الامامي |
| 07 Suspension System | | ممتص الصدمات |
| 07.A Arms | LOWR ARM UPPER ARM BUSHRES CUT | ازرع |
| 07.B Ball Joint | BOOT CUT | مفصل كروي |
| 07.C Shock Absorber | MODIFIED | ممتص الصدمات |
| 07.D Suspension Subframe | BODY LEVEL TOO LOWE & MODIFIED | |
| 07.E Other | STABILIZER LINK BOOT CUT | اخرى |
| 08 Chassis Condition | | الشاسي |
| 08.A Chassis | BOTH SIDE CHASSIS REPAIRED ,PORTION BEND,DENT ,BULGED | الشاسيه |
| 08.B Chassis Number | MANUFACTUR PLATE REFITTED & FADED, WINDSHIELD NUMBER MISSING | رقم القاعدة |
| 08.C Other | BOTH SIDE MOUNT REFITTED | اخرى |
| 08.D Chassis Extension | REAR BOTH SIDE BEND | تمديدات الشاسي |
| 09 Transmission Condition | | الجير |
| 09.A Visual Gear Box Condition | OPEN REFITTED OIL LEAK | حالة الجير النظري |
| 09.B Gear Box Mount | FRONT REAR MOUNT RUBBER CUT | كرسي الجير |
| 09.C DIFFERENTIAL | REFITTED OIL LEAK | الدفرنشيل |
| 09.D Propeller Shaft | REFITTED | ناقل الحركة |
| 10 Engine Condition | | المحرك |
| 10.A Other | AIR INTAKE PIPE MODIFIED | اخرى |
| 10.B Mount | BOTH SIDE MOUNT RUBBER CUT | كرسي |
| 10.C Visual Engine Condition | OPEN REFITTED OIL LEAK | حالة المحرك النظري |
| 10.D Modification | MODIFIED | تعديلات |
| 11 Steering Condition | | المقود |
| 11.A Steering Oil | MINOR OIL LEAK , | زيت المقود |

DEFECT

REMARKS

12 Exhaust System**نظام العادم**

12.A Modification

MODIFIED

تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.