CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945048
Transaction Date	05 Nov 2026, 13:01:51
Site Name	840 - Emirates Auctions
Transaction Number	95340285 (CC10026) (CC10026)



Vehicle Details

Chassis Number	1N4AL2A98B*******
Specification	GCC Specification
Make	Nissan
Model	Altima
Model Year	2011
Color	Grey
Mileage	607024 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE & REAR LEFT SIDE REPAINTED PORTION REPIRED , FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENTS SCRATCHES, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR THICK RUST PROOFED MINOR DENT	الارضية
01.E Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.F Pillars	LEFT SIDE C/PILLAR ROCKER PANEL REPAIRED	القوائم
01.G Sign of side accident		وجود مؤشر لحادث في الجانب
01.H Vehicle Color	LIGHT BLUE	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
02.B Chassis Number	DOOR POST MANUFACTURE STICKER DAMAGE	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY , MINOR JERKING	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Other	CENTER WHEEL HUBS COVER MISSING	اخري
05.D Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	WATER TANK EMPTY & COVER MISSING	ازرع المساحات والشفرات
07 Lights		الاضاءة
07.A Head Light	LENS FADED & LEFT SIDE CRACK	الاضاءة الرئيسية
08 Steering Condition		المقود
08.A Steering Oil	MINOR OIL LEAK	زيت المقود
08.B Other	STEERING OIL RESERVIOR TANK EMPTY	اخري
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
09.B AC Condition	LOW COOLING	المكيف
09.C Dash Board	WORN OUT PORTION MELTED	لوحة القياده
09.D Steering Wheel and control buttons	PORTION DAMAGE , HARD	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
09.F Engine Start Button	REMOTE PORTION DAMAGE	زر تشغيل المحرك
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae