





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20204251	Plate Category	: PRIVATE
Transaction Date	: 11 JUL 2020 09:52:23	Plate Number	: 367537 EA
Queue Number	: 193774	Import Doc. Ref.	:
Chassis Number	: WGY60367537	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 1993
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Failed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.02 - Tail Lights		الانوار الخلفية
		BOTH SIDE LENS BROKEN/FRONT SIGNAL & SIDE LIGHTS CRACKED
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		DOT 1517
04.07 - Rims		الرنجات
		STUD BROKEN & BOLT MISSING
05 Body		الهيكل
05.04 - Fenders		المدكار
		REAR BOTH FENDER/FIREWALL REPAIRED
05.05 - Bumpers		الدعامية
		BUMPER GRILL PARTLY BROKEN
05.07 - Floor		الارضية
		UNDERNEATH PORTION RUSTY & BOTH STEEPING BOARD BRACKET/RUSTY & CRACKED
05.08 - Chassis (Frame)		الشاصية
		FRONT RIGHT END/REAR BOTH CHASSIS BULGED & DENT/REAR TOW HOOK DENT & PORTION RUSTY
06 General Items		الاشياء العامة
06.02 - Wiper Arms		اذرع ماسحات الزجاج
		MOTOR MISSING & FIREWALL PARTLY RUSTY
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
		DRIVER SEAT BACK REST COVER MISING/DOOR & REAR SIDINGS & COVER PARTLY TORN& MISSING
06.13 - Exhaust System		نظام العادم
		CUT & WELDED
06.14 - Transmission Condition		حالة ناقل الحركة
		OIL LEAK & BELL HOUSING RUSTY/CRACKED
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		OIL PAN DENT/ENGINE VIBRATION
06.21 - Battery Condition		حالة البطارية
		BRACKET MISSING



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20204251	Plate Category	: PRIVATE
Transaction Date	: 11 JUL 2020 09:52:23	Plate Number	: 367537 EA
Queue Number	: 193774	Import Doc. Ref.	:
Chassis Number	: WGY60367537	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 1993
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

#### Statement of Vehicle Condition

07 Remarks		ملاحظات
07.04 - Others	199300 KM	ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident	BUMPER/BULKHEAD/FENDER/BONNET REPAIRED	أثر حادث في مقدمة المركبة
09.18 - A/C Not Cooling	LOW COOLING	عطل في المكيف
09.24 - Digital Display Damaged/Warning Lights	SPEEDOMETER GUAGE NOT WORKING	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted		أثر صبع في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p>		

# Test Certificate



**FAILED**

Plate Details :	--
Chassis No :	WGY60367537
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	199300 Kms.
Origin : Japan	Model Year : 1993
Gear Type : --	Engine Size : 3600 CC
Engine No : TB42023862	Horse Power : --
Axles No : 2	Cylinders : 6
No Of Doors : 4	No Of Seats : 5
G. V. W. : 2850 Kgs.	Empty Weight : 2000 Kgs.

Certificate Number :	5-TAS-2020-12140694
Inspection Date :	12-07-2020
Certificate Print Date :	12-07-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	36 min 0 sec
Appointment Ref Number :	--
Start Time : 11:43	End Time : 12:19
Lane : 01	Token No. : 3
Attempt : 1	Prints No : 1

### Parameter Readings

Service brake imbalance on front axle 1%	Service brake imbalance on rear axle 6%	Parking brake imbalance between LHS and RHS 24%	Vehicle on Petrol CO Reading 1.43%
Vehicle on Petrol HC Reading 109 PPM VOL			

### Inspection Findings

Defects	Issue	Severity
Battery FIX BRACKET	Unsecure	Major
Wiper arms, Blades, Washer NOT WORKING	Defective wiper motor	Major
Park and Tail lamps RIGHT SIDE LENS BROKEN	Lens cracked, broken or faded (Major)	Major
Rim FIX ALL MISSING TIRE BOLT & NUT	Missing bolts and nuts (Major)	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3600	4800	

### Inspection Remarks:

FRONT RIGHT END/REAR BOTH CHASSIS BULGED & MINOR DENT/REAR TOW HOOK DENT/BUMPER/BULKHEAD/FENDER/BONNET REAR BOTH FENDER/FIREWALL MIDDLE LEFT SIDE FLOORING REINFORCEMENT REPAIRED