CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2902358
Transaction Date	24 Oct 2026, 12:13:52
Site Name	840 - Emirates Auctions
Transaction Number	87968422 (CC10013) (CC10011)



Vehicle Details

Chassis Number	1GCVK9EC3E*******
Specification	GCC Specification
Make	Chevrolet
Model	Silverado
Model Year	2014
Color	White
Mileage	458638 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REPAINTED PORTION REPAIRED,RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED PORTION STICKER MINOR DENTS SCRATCHES , PORTION RUSTY HOLE	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED REPAIRED,REAR REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.F Bumper	MISALIGN,SCRATCHES	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	RIGHT SIDE C/ PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	CABIN,TAIL GATE REPAINTED PORTION REPAIRED	صندوق
01.J Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	VIN NUMBER REPUNCH / CHASSIS FRAME RUST PROOFED PORTION DENT BULGED RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL WET , MUDDY , DIRTY , REFITTED , PARTS GETTING RUSTY , ABNORMAL NOISY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED , REAR HEADREST MISSING	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	DELAY SHIFTING , JERKING , REFITTED , PARTS GETTING RUSTY , MUDDY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 204	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Leaf Spring	MISALIGN , BUSHES DRY CRACK	
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Steering Boot	BOOT CUT LEAK	ربلة المقود
08.B Tie Rod End	BOOT CUT	مؤخرة الرودات
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
09.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING PORPERLY	المرايا
09.C AC Condition	OK	المكيف
09.D Roof Ceiling	MINOR CUT	بطانه السقف
09.E Sun Visor	RIGHT SIDE MIRROR COVER MISSING	حاجب الشمس
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae