



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 May 2023, 16:28:21
Transaction Number	36078471 (CC10010)	Queue Number	716245



Chassis Number	1ZVBP8JZ1E5269048
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Mustang
Model Year	2014
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Floor	PORTION DENT.	الارضية
01.B Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Paint	BODY PORTION REPAIRED ,PORTION REPAINTED ,DENTS SCRATCHES ,PORTION FADED ,	الصبغ
01.D Bumper	MISALIGN ,PORTION DAMAGE.	دعامية
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2019 CRACKED.	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2019 CRACKED.	الاطار الخلفي
03 Exhaust System		نظام العادم
03.A Modification	MODIFIED & REAR BOTH SIDE MUFFLER MISSING.	تعديلات
04 Interior Condition		الحالة الداخليه
04.A Odometer reading	NOT CHECKED .	قراءة عداد المسافات
04.B AC Condition	NOT CHECKED .	المكيف
04.C Other	INTERIOR RUSTY.	اخرى
04.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم

DEFECT	REMARKS	
05 Suspension System ممتص الصدمات		
05.A Shock Absorber	WEAK,LEAK.	ممتص الصدمات
05.B Arms	LOWER ARM BUSHES CRACKED.	ازرع
06 Steering Condition المقود		
06.A Steering Box	OIL LEAK,	جهاز المقود
06.B Steering Boot	CUT.	ربلة المقود
06.C Axle	BOOT CUT.	اكسلات
07 Engine Condition المحرك		
07.A Other	AIR FILTER MODIFIED.	اخرى
07.B Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,REFITTED .OIL LEAK.PARTS MISSING,	حالة المحرك النظرى
08 Transmission Condition الجير		
08.A Visual Gear Box Condition	NOT CHECKED,REFITTED,OIL LEAK.	حالة الجير النظرى
08.B Road Test	NOT CHECKED,	فحص علي الطريق
08.C DIFFERENTIAL	OIL LEAK.	الدفرنشيل
09 Brake Condition الفرامل		
09.A Disc&Drum	RUSTY,	دسك ووطنابير الفرامل
10 Lights الاضاءة		
10.A Head Light	LENS FADED,ALL LIGHT NOT CHECKED.	الاضاءة الرئيسية
11 Chassis Condition الشاصي		
11.A Chassis	CHECKED ONLY VISIBLE AREA OK.	الشاشيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.