

Queue Number

2614189

Transaction Date

03 Aug 2026, 13:56:51

Site Name

840 - Emirates Auctions

Transaction Number

84550044 (CC10021) (CC10011)



Vehicle Details

Chassis Number	W1K5J5BB2M*****
Specification	GCC Specification
Make	Mercedes
Model	CLA
Model Year	2021
Color	Grey
Mileage	77432 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED,REFITTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR,ENGINE,GEAR BOX COVERED,CHECKED VISIBLE ARAE ONLY	الارضية
01.F Bumper	MISALIGN,PORTION CRACKED	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.H Trunk	REAR SWITCH NOT WORKING STUCK	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS REFITTED,GETTING RUSTY,SHAKING,MISFIRING,RPM NOT STABLE	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER	حالة المقاعد
---------------------	-------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	---------------------	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Interior Condition		الحالة الداخلية
08.A Other	CENTER CONSOLE BOX COVER WORN OUT CRACKED	اخرى
08.B Mirror	CENTER VIEW MIRROR BACK COVER PART MISSING	المرآيا
08.C AC Condition	OK	المكيف
08.D Roof Light	SWITCH PORTION FADED	أنارة السقف
08.E Power Window Switch And Glass	FRONT LEFT SIDE QUART GLASS CHROME MISSING	مفتاح النافذه و الزجاج
08.F Audio	CENTER SWITCH PANEL PORTION FADED	صوتيات
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Sunroof	NOT WORKING,CURTAIN PORTION DAMAGED	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae