

Queue Number

2648833

Transaction Date

15 Aug 2026, 11:37:15

Site Name

840 - Emirates Auctions

Transaction Number

97052587 (CC10021) (CC10011)



Vehicle Details

Chassis Number	5N1CR2M80K*****
Specification	GCC Specification
Make	Nissan
Model	Pathfinder
Model Year	2019
Color	White
Mileage	147058 Km
Fuel Type	Hybrid
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED REPAINTED,EXCEPT ROOF BONNET,MINOR DENT SCRATCHES	الصبغ
01.B Doors	BEADING LOOSE	أبواب
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Bumper	MISALIGN,PORTION DAMAGED,PART MISSING	دعامية
01.E Roof	PORTION MODIFIED HOLES	السقف
01.F Bonnet	REFITTED	غطاء المحرك
01.G Pillars	INNER COVER PORTION LOOSE DAMAGED,ROCKER PANEL COVER PARTS MISSING	القوائم
01.H Trunk	INNER,OUTER COVER PORTION DAMAGED PARTS MISSING,LOGO MISSING	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED,PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	REAR SEATS MISSING,DRIVER SEAT SIDE COVER LOOSE	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY,MINOR OIL LEAK	الحالة النظرية للجير
--------------------------------	---	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHTS,MESSAGE ON DISPLAY	ضوء تحذير
07.C Fog light	MISSING	كشف الضباب
08 Suspension System		ممتص الصدمات
08.A Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX PANEL PORTION MODIFIED HOLES, INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
09.B AC Condition	OK,FRONT SWITCH PANEL,MIDDLE GRILL MODIFIED,GRILL DAMAGED	المكيف
09.C Power Window Switch And Glass	REAR BOTH SIDE SWITCH PANEL MISSING	مفتاح النافذه و الزجاج
09.D Floor Matting	PORTION DAMAGED	فرش الأرضيه
09.E Audio	STEREO MODIFIED PORTION DAMAGED	صوتيات
09.F Dash Board	PORTION DAMAGED,MODIFIED	لوحة القيادة
09.G Roof Ceiling	PORTION CUT LOOSE	بطانه السقف
09.H Door Panel	REAR BOTH SIDE MISSING	لوحة بطانة الباب
09.I Steering Wheel and control buttons	WORN OUT,HORN NOT WORKING	عجلة القيادة وازرار التحكم
09.J Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات
09.K Engine Start Button	WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae