

TEST CERTIFICATE

حالة المحرك النظرى

Site Number
Transaction Number

04.A Visual Engine Condition

840-Emirates Auctions 50439941 (CC10008) Transaction Date

16 Aug 2022, 14:08:33

Queue Number

312309



Chassis Number **1N4AL3AP6GC100756**

Engine Number

Vehicle Class Car

Manufacturer Nissan

Model Altima

Model Year 2016

Color White

Mileage **185403 Km**

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

DEFECT REMARKS

| O1 Body | | جسم المركبة |
|-----------------------------------|--|-------------------|
| 01.A Fenders | FRONT RIGHT SIDE PORTION REPAIRED, REPAINTED & REAR RIGHT SIDE PORTION REPAINTED | مدکار |
| 01.B Paint | BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES | الصبغ |
| 01.C Bumper | MISALIGN | دعامية |
| 01.D Trunk | PORTION REPAINTED | صندوق |
| 02 Tires and Rims Condition | | الاطارات |
| 02.A Front Tyre | BOTH SIDE 2020 | الاطار الامامي |
| 02.B Rear Tyre | BOTH SIDE 2020 | الاطار الخلفي |
| 03 Transmission Condition | | الجير |
| 03.A Road Test | NOT CHECK | فحص علي الطريق |
| 03.B Visual Gear Box Condition | MINOR OIL LEAK | حالة الجير النظرى |
| 03.C Gear Box Mount | MOUNT RUBBER CUT | كرسي الجير |
| 04 Engine Condition | | المحرك |

MINOR OIL LEAK

| DEFECT | REMARKS | |
|---|-------------------------|----------------------------|
| 04.B Mount | MOUNT RUBBER CRACKED | كرسي |
| 05 Chassis Condition | | الشاصي |
| 05.A Chassis | CHECKED VISIBLE AREA OK | الشاسيه |
| 06 Suspension System | | ممتص الصدمات |
| 06.A Arms | LOWER ARM BUSHES CUT | ازرع |
| 06.B Ball Joint | BOOT CUT | مفصل كروي |
| 07 Steering Condition | | المقود |
| 07.A Tie Rod End | BOOT CUT | مؤخرة الرودات |
| 08 Interior Condition | | الحاله الداخليه |
| 08.A AC Condition | ОК | المكيف |
| 08.B Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.